DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : Ottawa County Farms Landfill							SRN :	N3294	
Location: 15550 68th Avenue							District :	Grand Rapids	
								County :	OTTAWA
City :	COOP E	ERSVILL	State:	MI	Zip Code :	49404	Comp Status		Compliance
Source C	Class :	MAJOR					Staf	if: David	Morgan
						FCE Date	Completion	9/13/2018	
Commer	nts :								

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments	
08/30/2018	Scheduled Inspection	Compliance		
06/12/2018	MACT (Part 63)	Compliance	MI-ROP-N3294-2013. SSM Report (Subpart AAAA)- During the reporting period, there were 20 startup, 11 shutdown and 0 malfunction events documented. The company indicated that all provisions of the SSM Plan were followed during the reporting period. SSM records are maintained on site and no changes were made to the plan.	
06/12/2018	ROP SEMI 2 CERT	Compliance	The company reported two deviations. The there were eight wells that exhibited oxygen or pressure exceedances that could not be resolved in 15 days. In all cases, the company took corrective actions including installing new wells and redriling others. Alternate timeline approvals were approved by AQD. Original signatures for the responsible official were provided.	
06/12/2018 NSPS (Part 60)		Compliance	Semiannual Compliance for Subpart WWW. Semiannual Compliance for Subpart WWW. The company fulfilled its semiannual NSPS report responsibilities.	

Activity Date	Activity Type	Compliance Status	Comments
06/12/2018	ROP Annual Cert	Compliance	Company submitted annual compliance certification in accordance with ROP No. MI- ROP-N3294-2013. The report was certified with an original signature by the responsible official. All deviations are reported.
05/18/2018	ROP Tech Review Notes		
05/07/2018	MAERS	Compliance	This MAERS is acceptable and emissions as expectedDLM
09/13/2017	ROP Semi 1 Cert	Compliance	The company reported two deviations. The there was one well that exhibited oxygen or pressure exceedances that could not be resolved in 15 days. The company took corrective actions by installing a new lateral line. An alternate timeline was ultimately approved by AQD. Original signatures for the responsible official were provided.

.

Name: Date: 9/13/18 Supervisor:

Page 2 of 2