DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility :	Metal Technologies, Inc. Three Rivers Gray Iron				SRN:	B2015	
Location :	429 Fourth Stre	et				District :	Kalamazoo
						County:	SAINT JOSEPH
Clty: T	HREE RIVERS	State: MI	Zip Code :	49093	Comp Status		Compliance
Source Class	s: MAJOR				Staf	f: Amand	la Chapel
FCE Begin D	ate: 8/1/2019			-	FCE Date	Completion	8/14/2020
Comments :							

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
08/12/2020	Scheduled Inspection	Compliance	
07/06/2020	MACT (Part 63)	Compliance	Notification as required per 40 CFR 63.7750(d) for the semiannual opacity performance test as required by 40 CFR 63.7731(b). The Method 9 performance test had no issues.
06/11/2020	Records Review (In office)	Compliance	
04/02/2020	ROP Annual Cert	Compliance	Facility submitted the report with an ROP certification form with an original signature and date from the responsible official. The facility reported a malfunction with the EUSHAKEOUT and North Dustar dust collector. The North Dustar blew a fuse. Plant manager ordered the facility to cease operations until it was fixed. The estimated time the EU ran was 1.25 hours without the dust collector running properly. They have since added an interlocking system which will automatically shut down any process in the plant if an associated DC malfunctions.
04/02/2020	ROP SEMI 2 CERT	Compliance	Facility submitted the report with an ROP certification form with an original signature and date from the responsible official. The facility did not report any deviations during the reporting period.

Activity Date	Activity Type	Compliance Status	Comments
04/02/2020	MACT (Part 63)	Compliance	Iron and Steel MACT Standard, 40 CFR 63 Subpart EEEEE Semiannual Certification Facility submitted the certification with the ROP Annual and Semi-Annual certification which contained an original signature and date from the responsible official. The facility reported no known MACT deviations during this period.
:	CAM Excursions/Exceedan ces	Compliance	EGLE Compliance Assurance Monitoring (CAM) Excursion/Exceedance Summary Report Facility submitted the CAM EER with the ROP Semi-Annual certification which contained an original signature and date from the responsible official. The facility reported no excursions or exceedances during this time.
04/02/2020	CAM monitor downtime	Compliance	EGLE Compliance Assurance Monitoring (CAM) Monitor Downtime Incident Summary Report Form Facility submitted the CAM downtime summary with the ROP Annual and Semi-Annual certification which contained an original signature and date from the responsible official. The facility reported no CAM monitor downtime or incidents.
04/02/2020	ROP Other		Facility submitted an updated Air Pollution Control Plan consisting of the (1) capture system, baghouse leak detection system, and control device O&M plan, (2) PMP (3) scrap certification and selection plan, (4) startup, shutdown, and malfunction abatement (SSM) plan, (5) Compliance assurance monitoring (CAM) plan
03/12/2020	Complaint Investigation	Non Compliance	

Activity Date	Activity Type	Compliance Status	Comments
08/07/2019	MACT (Part 63)	Compliance	Iron and Steel MACT standard, 40 CFR 63 Subpart EEEEE Semiannual Certification
			Facility submitted the certification with the ROP Semi-Annual certification which contained an original signature and date from the responsible official. The facility reported no known MACT deviations during this period.
08/07/2019	CAM Excursions/Exceedan ces	Compliance	MDEQ Compliance Assurance Monitoring (CAM) Excursion/Exceedance Summary Report Form No CAM exceedances were
00/07/0040	OANE	0 1	reported.
08/07/2019	CAM monitor downtime	Compliance	MDEQ Compliance Assurance Monitoring (CAM) Monitor Downtime Incident Summary Report Form
			Facility reported downtime on the differential pressure monitor on 5/5, 5/7, and 5/14 which was caused by a bad gauge hose. The hose has been repaired.
08/07/2019	ROP Semi 1 Cert	Compliance	Report contains an original dated ROP certification report by the facility's responsible official. The report stated that there were no know deviations from 40 CFR Part
			63, Subpart EEEEE during the reporting period. The facility reported one deviation on EUSHAKEOUT on 1/29/19 for 1.25 hours. The North Dustar blew a fuse. The plant manager
			ordered the facility to cease operations until it was fixed. The estimate is that the EU ran for 1.25 hours without the dust collector in operation. The facility
			added interlocking that will automatically shut down any process in the place associated with DC malfunctions.

Activity Date	Activity Type	Compliance Status	Comments
08/07/2019	ROP Other	Compliance	Department received an updated copy of the Air Pollution Control Plan revised on July 2019. It includes: Capture System, Baghouse Leak Detection System, and Control Device System O&M Plan; Preventative Maintenance Plan, Scrap Certification and Selection Plan; Startup, Shutdown, and Malfunction Abatement Plan; and Compliance Assurance Monitoring Plan.

Name: <u>()</u> Date: <u>8/14/2020</u>

Supervisor: