

STAFF REPORT

Michigan Department of Environment, Great Lakes, and Energy

- | | | | |
|---|--|---|--|
| <input type="checkbox"/> Hazardous Waste/Pt.111 | <input type="checkbox"/> Liquid Ind.Waste/Pt.121 | <input type="checkbox"/> Complaint Inspection | <input type="checkbox"/> Corrective Action |
| <input type="checkbox"/> Solid Waste/Pt.115 | <input type="checkbox"/> Scrap tire/Pt.169 | <input checked="" type="checkbox"/> Compliance Inspection | <input type="checkbox"/> Sampling Inspection |
| | <input type="checkbox"/> Other _____ | <input type="checkbox"/> Construction/Closure Inspection | <input type="checkbox"/> Telephone Call |
| | | <input type="checkbox"/> Permitting Inspection | <input type="checkbox"/> Meeting Notes |
| | | <input type="checkbox"/> PEAS Investigation | <input type="checkbox"/> Other _____ |

Facility/Site Name Arbor Hills Landfill	Date/Time 6-7-24 8:55am to 10:45am
Address 10699 W. Six Mile Road	Facility/Site Number WDS 475946
Participants/Contacts Dave Seegert	Staff Gary Schwerin

REFERRED TO:
REMARKS (weather, unusual conditions, etc.): 63 ^o , partly cloudy, wind W 7mph. Times are rounded to the nearest 5 minutes.
I arrived on-site at 8:55am to complete an odor inspection after receiving odor complaints.
I completed inspections and made the noted observations at the following locations
49920 Parkside Drive – Light (1) garbage odor at 9:00am
16420 Ridgewood Court – Light (1) garbage odor at 9:10am
49114 Rainbow Lane – Light (1) garbage odor at 9:20am
Napier Road along the landfill – strong (3) garbage odor at 9:30am. Odor mitigating fans were running.
I called Dave Seegert at 9:41am and told him about the strong odors on Napier Road. Dave said he would have someone check the fans and start putting deodorant on the active face.
49856 Parkside Drive – Light (1) garbage odor at 9:45am
Napier Road along the landfill – still a strong (3) garbage odor at 10:15am. Odor mitigating fans were running.
I left the site at 10:15am.
I returned to Napier Road at 10:45am and detected strong (3) garbage odors and noticed the fans were not running.
The odor mitigating fans are not located downwind from the active filling area. There were strong odors downwind from the fans as well as north and south of the fans along Napier Road adjacent to the landfill.
I left at 10:45am

