

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Self Initiated Inspection

N132854204

FACILITY: Rec Boat Holdings LLC - Cruiser Plant		SRN / ID: N1328
LOCATION: 609 13 TH. St., CADILLAC		DISTRICT: Gaylord
CITY: CADILLAC		COUNTY: WEXFORD
CONTACT: Trent Burch , Environmental/Safety Compliance		ACTIVITY DATE: 07/09/2020
STAFF: Sharon LeBlanc	COMPLIANCE STATUS: Non Compliance	SOURCE CLASS: MAJOR
SUBJECT: Site visit to check condition of Wyse joints on stacks. Maintenance work is required on central stack. sgl		
RESOLVED COMPLAINTS:		


On July 9, 2020, AQD District Staff conducted a self-initiated site inspection of the Rec Boat Holdings LLC - Cruiser Plant located at 609 13th street, Cadillac, Michigan. The intent of the inspection was to determine if the existing stacks were in good condition, and verify if any damage existed at the wyse joints to the stacks. District staff met with Mr. Trent Burch regarding concerns of damage to stacks.

An initial drive by along 13th street in front of the building indicated that there were dark spots and rust at multiple spots along the two eastern most stacks. Observations made from the parking lot below the two eastern stacks identified locations where it appeared that the metallic (foil?) exterior coating of a rubber band used at stack joins was peeling, and exposing the black rubber. At at least one location on the center stack it appeared that the black rubber had torn, but that the tear did not extend to the point of a leak, however at a lower wyse joint it was clear that the damage to the rubber at that location had resulted in a hole that needed immediate attention. Mr. Trent indicated that a work order would be prepared for the required work, and that if the banding was instock that the repairs would be made yet this week. If the material was not in stock it would be ordered and installed as soon as possible.

Mr. Burch is to follow up with a tentative schedule for the repairs, and pictures of the repaired locations.



**Image 1(view from west) :** View of two eastern most stacks and wyse joints from across 13th street.



**Image 2(central stack)** : view of stack and wyse joints for central stack. Note the metallic coating of rubber banding at joints is coming off.

NAME \_\_\_\_\_

DATE \_\_\_\_\_

SUPERVISOR \_\_\_\_\_

Sharon  
LeBlanc

Digitally signed by  
Sharon LeBlanc  
Date: 2020.07.15  
08:27:23 -04'00'

Shane  
Nixon

Digitally signed by  
Shane Nixon  
Date: 2020.07.15  
08:27:50 -04'00'