DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Self Initiated Inspection

FACILITY: NORTHSTAR CRUSHING AND SCREENING INC		SRN / ID: N7758
LOCATION: N4501 HIGHWAY M-95, IRON MOUNTAIN		DISTRICT: Upper Peninsula
CITY: IRON MOUNTAIN		COUNTY: DICKINSON
CONTACT: Josh Nyquist, Or	erator	ACTIVITY DATE: 06/03/2015
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced ins	pection of portable crusher to determine compliance wil	th PTI# 32-07.
RESOLVED COMPLAINTS:		

INSPECTION DATE: 6/03/2015

DEQ STAFF: Joseph Scanlan, EQA

FACILITY: Portable Crusher PTI#32-07

FACILITY OWNER:

Northstar Crushing & Screening			
Josh, Curt, and Bonnie Nyquist			
8541 N. 3 Lane			
Box B			
Gladstone, MI 49827			

LOCATION: The crusher was located at the Boyer Pit, Trenary, Alger County.

<u>EU DETAIL/REGULATIONS</u>: The most recent piece of equipment added is a transfer conveyor labeled as emission unit ID No. 16, however this new conveyor was not at the site where the crusher operations were taking place when inspected. The following is an updated equipment list:

EQUIPMENT LIST

EU	Description	VE Test Date
A*	Jaw Crusher	7/25/2007
C*	Cone Crusher	7/25/2007
D	Screen	9/20/2007
E E	Screen	Unknown
	Crusher	Unknown
G	Cone Crusher	Unknown
2*	Stacker Conveyor	7/24/2007
3 •	Conveyor	9/20/2007
4	Conveyor	7/24/2007
7*	Conveyor	5/2011
8	Feeder	Unknown
9	Солveyor	Unknown
10	Conveyor	Unknown
11	Conveyor	Unknown
12	Conveyor	Unknown
13	Conveyor	Unknown
14*	Radial Stacker Conveyor	Unknown

15	Hopper/Conveyor	Unknown
	Radial Stacker Conveyor	5/6/2010

^{*} Denotes equipment onsite during inspection.

INSPECTION: I met with crusher owner Mr. Curt Nyquist upon getting to the site. Curt introduced me to his son, Mr. Josh Nyquist, who handles permit compliance. Josh informed me that there were two other employees on site at the time in addition to he and his father. The crusher was operating during my inspection; I noticed no discernible fugitive dust emissions. Josh provided me with a copy of the PTI# 32-07 which was located in their equipment trailer. I noted that identification for Conveyor #7 had deteriorated to the point of being indiscernible, and Josh immediately had an employee paint a new number on the unit.

<u>SUMMARY</u>: I observed no violations of PTI# 32-07 or state air pollution control rules during my inspection.




Image 1(NS1): Radial stacker conveyor EU_14





Image 2(NS2): Radial stacker conveyor EU_14



<u>Image 3(NS3)</u>: 1000 gallon water tank/trailer. Conveyor EU_2 is behind the water tank.



Image 4(NS4) : Cone Crusher EU_C



Image 5(NS5) : Jaw Crusher EU_A




Image 6(NS6): Screen and conveyors

NAME Joseph Jeanson

DATE 7 16 15

SUPERVISOF