

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

P012445370

FACILITY: Admiral Petroleum		SRN / ID: P0124
LOCATION: 919 S Main St, EATON RAPIDS		DISTRICT: Lansing
CITY: EATON RAPIDS		COUNTY: EATON
CONTACT: Jim Sova, Senior Project Manager		ACTIVITY DATE: 07/25/2018
STAFF: Michelle Luplow	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Announced, scheduled inspection to determine compliance with General PTI 127-10.		
RESOLVED COMPLAINTS:		

Inspected by: Michelle Luplow

Admiral Petroleum Remediation contact: Jim Sova, Crawford Environmental Services, Senior Project Manager
(jsova@crawfordenvironmental.com)

Purpose

Conducted an announced, scheduled compliance inspection of Admiral Petroleum's SVE and air sparging remediation system, located at an operational Admiral Petroleum gas station, to determine compliance with General PTI No. 127-10. This facility was last inspected July 2013.

Facility Background/Regulatory Discussion

During the 2013 inspection, David Hopp, Environmental Consultant was managing the remediation of this property. Jim Sova, Crawford Environmental Project Manager, said that this site was transferred over to Crawford Environmental in 2017, but with no emissions records from the previous consultant. He provided me with historical documents showing that sometime between the July 2013 inspection and April 2014 the system was removed (see attachments).

I contacted J. Sova prior to the inspection, who stated that there is currently no active system onsite and I arranged for J. Sova to meet me at the site.

Inspection:

On July 25, 2018 I met with J. Sova at approximately 10:30 a.m. at the remediation site. I emailed him an electronic copy of the January 2017 Permit to Install exemptions handbook, as well as the 2013 inspection report and PTI 127-10.

I verified with him that the air sparging equipment had been removed. There were only 2 concrete slabs present, in addition to the electrical feed conduit and 3 well heads. See attached photos.

I will request that PTI 127-10 be voided because the equipment has been removed from the site



Image 1(Concret Slab #1) : Facing north




Image 2(Concrete Slab #2) : Facing South




Image 3(Wellheads) : 3 wellheads still present



Image 4(Electrical Conduit) : Conduit for electricity to power system.

NAME Mitchell Spivey

DATE 7/31/18

SUPERVISOR B.M.

