Great Lakes Cremation Inc. 29547 Costello Dr. New Hudson, Mi. 48165 (248) 667-9344

Eucrematory 1 Violation Resolution letter

hand the grant of the second s	·····)
MAY 0 4 2021	
Air Quality Division Warren Office	and a second state of the

Date of Malfunction: 2/3/2021-2/10/2021

Cause: There was a low flow of air going to the secondary combustion chamber.

Corrective action: Machine was shut down on 2/10/2021. On 2/11/2021, Gil Pietrandrea made adjustments on the nozzle to create a better flow of air. He also made an adjustment to the belimo to make the air flow stronger.

Preventative measures: We are monitoring the temperature in in the chambers. If the temperature inside of the chamber is below 1600 degrees, the machine will be shut down until adjustments are made.