

Young

*Colonial Chapel
Funeral Home, Inc.*

*4061 St. Clair Hwy.
China, MI 48054
(810) 329-4766*

*Randall S. Young
Owner – Manager
fax (810) 329-0179*

P0187 B&E
RECEIVED
DEC 14 2016
AIR QUALITY DIVISION
SEMI OFFICE

December 12, 2016

Department of Environmental Quality
Air Quality Division
Attn: Mr. Robert Elmouchi

Below please find the requested written response to the Violation Notice issued November 22, 2016.

Violation dates: September 30, 2015, August 18, 2016, August 23, 2016, August 31, 2016, September 15, 2016.

I have called Matthews Cremation and spoke with a technician and he had suggested that if there was a long interval, as in number of days, between cremations that the fire brick may not be fully retain the heat on the first run of the day. Each of these violations were on the first run of the day.

We have currently corrected these violations simply by the way we operate our machine. I have enclosed copies of our charts from November 15th to December 8th. These are cremations that have taken place following our conversations with Mr. Elmouchi and Matthews Cremation.

It was suggested to us by Matthews Cremation that the first cremation run of the day that we wait for the secondary combustion chamber to elevate to 1650 degrees and turn the throat air off before we begin the cremation process. We have found their suggestions successful in achieving the required temperature in the secondary combustion chamber.

If there are any further questions or suggestions please call.

Thank you,



Randy Young