

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

P124761146

FACILITY: Contour Development LLC		SRN / ID: P1247
LOCATION: 21500 Northwestern Highway, SOUTHFIELD		DISTRICT: Warren
CITY: SOUTHFIELD		COUNTY: OAKLAND
CONTACT:		ACTIVITY DATE: 12/15/2021
STAFF: Robert Elmouchi	COMPLIANCE STATUS: Non Compliance	SOURCE CLASS: Minor
SUBJECT: Unannounced observations of unpermitted crushing equipment pending PTI approval. This facility is in non-compliance because the equipment has been installed and the PTI is pending approval.		
RESOLVED COMPLAINTS:		

On Wednesday, December 15, 2021, I conducted unannounced observations of the nonmetallic mineral crusher installation to determine if the emission unit was currently on site and if it was operating.

I arrived on site about 10:30 a.m. I parked in a business lot on Greenfield Road adjacent to the northwest corner of the construction site perimeter fence. I observed the construction site and activities through the fence from a safe location. I observed a bulldozer and excavator in use. I saw the nonmetallic mineral crusher, conveyer, and screener, which did not appear to be operating. I noticed that the piles of material adjacent to the crusher contained large chunks of concrete and asphalt, which appeared to indicate that these piles had not been processed by the crusher. I did not see piles of crushed materials on the construction site. Therefore, it appears that Contour Development LLC has not been operating the crusher since the initial trial and notification of noncompliance around November 12, 2021.

This facility is not in compliance because the PTI application, which was submitted in response to a violation notice, is pending approval.



Image 1(IMG 7428 cropped) : Image from complainant of unpermitted nonmetallic mineral crushing activity. This image was received on 11/12/2021.



Image 2(IMG 0287 cropped) : Photo of nonmetallic mineral crusher taken by the AQD on 12/15/2021 during an unannounced site observation. The large pieces of asphalt and concrete adjacent to the crusher appear to indicate that this material has not been processed.

NAME Robert Elmarachi

DATE 12/15/2021

SUPERVISOR Joyce