



VIOLATION RESPONSE

SRN:B3000,Macomb County

PTI No.186-91D

DATE:12/06/23

Process Description	Rule/Permit Condition Violated	Response
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition1.1	<ul style="list-style-type: none"> According to PTI No.186-91D Special Condition1.1 BPF maintains proper Chrome surface Tension and keeps daily record. The record is available anytime. The composite mesh pad has been ordered from Vanaire company. It will be delivered by 1/26/24.
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition III.1	<ul style="list-style-type: none"> The scrubber was down since January 1, 2023. Once BPF received & install the composite mesh pad then we will implement and follow-up the operation and maintenance plan.
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition IV.1	<ul style="list-style-type: none"> The composite mesh pad has been ordered however BPF perform chrome surface tension twice a day and all records are available.
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition IV.2	<ul style="list-style-type: none"> The composite mesh pad has been ordered from Vanaire company. It will be delivered by 1/26/24.
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition VI.3	<ul style="list-style-type: none"> BPF does not have 2nd and 3rd quarter inspection records because of scrubber was offline.
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition VI.4	<ul style="list-style-type: none"> The scrubber was offline, and all pressure drop record were at zero.
FGLINEIV-Nickel/Chrome plating line	PTI No.186-91D Special Condition VI.6	<ul style="list-style-type: none"> BPF did not have record due to the scrubber being offline since Jan 1,2023.