50000 Pontiac Trail, Wixom, MI 48393

Telephone: (248) 624-0000 | Fax: (248) 624-0506

Korex Corporation Violation Response and Corrective Actions

Date of Violation: October 10, 2024

Violations Noted:

Process Description	Rule/Permit	Comments
	Condition Violated	
Manufacturing Operations at Korex	PTI 539-96 Special Condition 3	Visible emissions were observed coming from the facility on 10/10/2024
Manufacturing Operations at Korex	Rule 336.1901	A distinct and definite objectionable odor (levels 3 and 4) was detected downwind from the facility due to the manufacturing operations at Korex Corporation

Corrective Actions:

PTI 539-96 Special Condition 3: Korex continued conversation with EGLE representative to further clarify emissions point as part of investigation. Investigation did not yield a definitive root cause for the occurrence. Korex taking a broad approach of continued PM planning, bag replacement, and observation to mitigate any further visible emissions and/or to identify root cause and correct.

Rule 336.1901: Per previous discussions with EGLE team, Korex continues to work with 3rd party assistance and recommendation on mitigation of odor release.

Corrective Actions Due Date:

PTI 539-96→ Ongoing. Action will not end, rather be standard practice/Rule 336.1901→ 12-31-2024

NOTE: Korex kindly requests that EGLE backs Korex in stating that the public is not to enter the property uninvited/unannounced as there are proprietary materials and processes happening. It was observed in October 2024 that a resident was observing our operations from the Korex employee parking lot. They were kindly asked to leave and advised they were not allowed to be there and complied without issue.

Collin Runhin

The **Korex** Corporation

50000 Pontiac Trail, Wixom, MI 48393 Telephone: (248) 624-0000 | Fax: (248) 624-0506