



November 20, 2015

Ms. Joyce Zhu
Senior Environmental Engineer
Michigan Department of Environmental Quality
Air Quality Division
3058 West Grand Boulevard
Detroit, Michigan 48202

**RE: RESPONSE OF DETROIT RENEWABLE POWER TO VIOLATION NOTICE
DATED NOVEMBER 9, 2015 ISSUED BY THE AIR QUALITY DIVISION**

Dear Ms. Zhu:

Detroit Renewable Power (“DRP”) submits this response to the November 9, 2015 Violation Notice (“VN”) issued by the Air Quality Division (“AQD”) of the Michigan Department of Environmental Quality received via e-mail on November 9, 2015. The VN alleges that DRP violated conditions of ROP No. MI-ROP-M4148-2014, Table FGBOILERS011-013, Condition I.11.

DRP provided a Rule 912 notification for the exceedances referenced above in an e-mail and hard copy addressed to you and dated November 6, 2015.


In response to the Violation Notice, DRP provides the following information:

1. Causes of the Violation
 - a. Slag build-up over the over-fire air nozzles
 - b. Incorrect damper positions
2. Actions that have been taken
 - a. Storm Technologies completed their combustion optimization report on November 16, 2015.
 - b. New refractory was installed in all three boilers. Completed on November 18th.
 - c. Damper positions have been verified and calibrated for all three boilers. Completed on November 20th.
3. Preventive Actions Proposed
 - a. Damper position verification will be part of every preventive maintenance outage going forward.

We trust that this letter provides a satisfactory response to the November 9, 2015 VN, but please contact me if you have additional questions or comments. We would be more than willing to meet with you or other AQD personnel at any time to discuss this response.

Yours truly,

DETROIT RENEWABLE POWER



Linwood Bubay
PRESIDENT

cc: Damian Doerfer, DRE