

**DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: On-site Inspection**

M427058256

<b>FACILITY:</b> PONTIAC MUNICIPAL CEMETERIES		<b>SRN / ID:</b> M4270
<b>LOCATION:</b> 6180 DIXIE HWY, CLARKSTON		<b>DISTRICT:</b> Warren
<b>CITY:</b> CLARKSTON		<b>COUNTY:</b> OAKLAND
<b>CONTACT:</b> Larry Robinson , Building Superintendent		<b>ACTIVITY DATE:</b> 04/27/2021
<b>STAFF:</b> Shamim Ahammod	<b>COMPLIANCE STATUS:</b> Unknown	<b>SOURCE CLASS:</b> MINOR
<b>SUBJECT:</b> Based on the onsite inspection, it is determined that the Pontiac Municipal Cemeteries is no longer using the emissions unit on this site and this permit should be voided. I will send an email request to Ms. Sue Thelen, of the AQD Permit Section, to void the PTI Nos. 62-70I and and16-85I. Hence, compliance with applicable requirements was not determined.		
<b>RESOLVED COMPLAINTS:</b>		

**On April 27, 2021, Michigan Department of Environment, Great Lakes and Energy-Air Quality Division (EGLE-AQD) staff, I (Shamim Ahammod) conducted an onsite schedule inspection of Pontiac Municipal Cemeteries (SRN: M4270) located at 6180 DIXIE HWY, CLARKSTON, Michigan. The purpose of the inspection was to determine the company's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Air Pollution Control Rules; and the conditions of PTI Nos. 62-70I and and16-85I.**

#### **Permit History and Source Description**

**On February 25, 1983, Permit to Install (PTI) No. 62-70I was issued for the installation and operation of the 300 pounds per hour Types O and 4 waste incinerators using a secondary burner.**

**On March 25, 1987, Permit to Install (PTI) No. 16-85I was issued for the installation and operation of the 150 pounds per hour Types 1 and 4 Industrial Equipment and Engineering Company incinerator with a secondary burner.**

#### **MACES records**

**On 2/28/2011, AQD received vendor document from permittee that appears to confirm that the power supply and gas supply have been disconnected from both incinerators.**

**On 01/11/2011, AQD staff received voice mail message that incinerators have been permanently disconnected.**

#### **Inspection Arrangement**

**Due to the COVID-19 pandemic, I prearranged this announced inspection on April 27, 2021.**

#### **Onsite Inspection**

**On April 27, 2021, at 1:10 PM, I arrived at the facility and was greeted by Mr. Larry Earl Robinson, Building Superintendent of City of Pontiac. Mr. Robinson's Phone number is 248-**

**758-3613 and email address is LRobinson@pontiac.mi.us. I introduced myself, provided credentials, and stated the purpose of the inspection.**

**During the inspection I observed the fuel and electrical supply lines were disconnected from both incinerators (Types 1 and 4 Industrial Equipment & Engineering Company incinerator and Types O & 4 waste incinerator). I took several pictures showing that fuel and electrical supply lines have been disconnected from both incinerators. Pictures are attached to this report.**

**Based on the onsite inspection, it is determined that the Pontiac Municipal Cemeteries is no longer using the emissions unit on this site and this permit should be voided. I will send an email request to Ms. Sue Thelen, of the AQD Permit Section, to void the PTI Nos. 62-70I and and16-85I. Hence, compliance with applicable requirements was not determined.**



**Image 1(Incinerators)** : fuel and electrical supply lines have been disconnected from both incinerators

NAME 

DATE June 1, 2021

SUPERVISOR 