Tuscola Energy, Inc.

920 North Water Street, Suite 213 Bay City, Michigan 48708

5/17/18

Mr. Ben Witkopp Air Quality Division Saginaw Bay District Office 401 Ketchum Street, Suite B Bay City, MI 48708

Re:

Response to April 26, 2018 Violation Notice: SRN N1586

Dear Mr. Witkopp

Below I have provided our responses to the Violation Notice.

Response to SRN N1586

| Allegation | Response |
|-------------------------|--|
| PTI No. 20-12A | This violation occurred on April 13, 2018. The separator has been |
| FGOILPRODUCTION SC IV.1 | repaired and there is no longer any leak We did notice that the dump |
| – H2S Leak on | valve would get stuck if not greased every day. In the past it was |
| EUNIXON4SEP separator | determined that there were smells coming from the separator, but as |
| tank. 82 ppm on meter | long as it was greased every day, there would be no leaks We then |
| | made it a point to grease the dump valve every day, which we thought |
| | stopped any leaks. |
| | |
| | The leaking part only leaks when it is automatic. We have changed the |
| | dump to only dump mechanically instead of automatically. Now there is no leak. |
| * | is no leak. |
| | We expect to have the leaking part replaced tomorrow. In case our |
| L. | mechanic is unable to have it repaired tomorrow, we should have |
| | enough time to have it fixed by next Friday 5/25/18. If it is still not |
| | repaired by then, we will shut in the Nixon Farm wells until it is fixed. |
| | |
| | Going forward I will assign a different employee to do our inspections |
| | as the prior employee has proven to be ineffective in finding sources of |
| , ž | leaks or shown any care in doing an accurate and honest job while |
| 1 | doing inspections. |

Please contact me if you have any questions.

Respectfully submitted,

Tuscola Energy, Inc.

By:

Jeffrey M. Adler - President