

DEPARTMENT OF ENVIRONMENTAL QUALITY  
 AIR QUALITY DIVISION  
**ACTIVITY REPORT: On-site Inspection**

N611859653

<b>FACILITY:</b> BREITBURN OPERATING LP- Colonel Saunders CPF		<b>SRN / ID:</b> N6118
<b>LOCATION:</b> SW14 SW14 SEC 29, CHARLTON TWP		<b>DISTRICT:</b> Gaylord
<b>CITY:</b> CHARLTON TWP		<b>COUNTY:</b> OTSEGO
<b>CONTACT:</b>		<b>ACTIVITY DATE:</b> 09/01/2021
<b>STAFF:</b> Becky Radulski	<b>COMPLIANCE STATUS:</b> Compliance	<b>SOURCE CLASS:</b> SM OPT OUT
<b>SUBJECT:</b> FY21 scheduled inspection		
<b>RESOLVED COMPLAINTS:</b>		

Traveled to N6118 Breitburn Colonel Saunders for an unannounced scheduled inspection to determine compliance with PTI 676-96. The inspection was a second attempt as the source has a locked gate and needed a key to access.

The dirt road access to the CPF is located on the north side of Sparr Rd, just east of Gingell Rd. There is a gate near the road with several padlocks.

The CPF was not operating during the inspection. The driveway appeared to be overgrown and unused for some time. A caterpillar engine was located in the building, a skid number was not located. Several small storage tanks were inside the building. A glycol dehydrator was located at the east end of the building with associated glycol tanks on the outside of the east wall. There was a lined tank farm on the south side of the building with two tanks, approximately 400 bbl.

Records were reviewed separately. Based on the scheduled inspection, the source appears to be in compliance with the permit conditions.

NAME \_\_\_\_\_

DATE \_\_\_\_\_

SUPERVISOR \_\_\_\_\_