

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N680138366

FACILITY: EnviroTech Coatings LLC		SRN / ID: N6801
LOCATION: 1900 Austin St, MIDLAND		DISTRICT: Saginaw Bay
CITY: MIDLAND		COUNTY: MIDLAND
CONTACT: Alan Popp, President		ACTIVITY DATE: 01/19/2017
STAFF: Sydney Bruestle	COMPLIANCE STATUS: Non Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Scheduled inspection to verify compliance with PTI 52-00C and all other applicable state and federal air quality regulations.		
RESOLVED COMPLAINTS:		

On January 19, 2017 I (Sydney Bruestle) conducted a scheduled onsite inspection at Enviro Tech Coatings located at 1900 Austin St, Midland MI. While onsite I met with owner/president Alan Popp and an employee, Pedro. Pedro gave me a tour of the facility and Mr. Popp showed me some emission records onsite and sent several spreadsheets via email.

The facility maintains an opt-out permit to install (PTI 52-00C) for Hazardous Air Pollutants (HAPs). Enviro Tech has a source wide VOC limit of 30 tpy. The facility currently operates 3 paint spray booths equipped with exhaust filters and high efficiency spray guns. They also operate a wheelabrator, which appears to be exempt from permitting. The booths all appeared to be operating in compliance with the PTI.

Enviro Tech Coatings is not in compliance with PTI 52-00C. I discovered several issues with the VOC and HAP emission records maintained onsite. Enviro Tech is not adequately tracking the following records: individual HAP emissions over a 12 month rolling time period; monthly usage rates (in gallons) of all reducers, cleanup solvents, and coatings; and monthly and 12 month rolling time period VOC emissions for each individual spray booth. In addition, the facility has also failed to maintain all records for a five year period, Enviro Tech is discarding records after 12 months. These issues have been ongoing, they were identified during the last inspection in April 2016 and remain unresolved. Enviro Tech has continuously failed to properly track individual HAPs and VOC emission rates.

To verify my findings I re-visited the Enviro Tech on January 26, 2017 to go over the record keeping issues I found with Mr. Popp. He noted the issues and has started assessing what steps are necessary to come into compliance with PTI 52-00C. I sent Enviro Tech a VN on January 31, 2017.

NAME



DATE

02/09/17

SUPERVISOR

