

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Self Initiated Inspection

A936436690

FACILITY: Hutchinson Antivibration Systems, Inc		SRN / ID: A9364
LOCATION: 600 Seventh St., CADILLAC		DISTRICT: Gaylord
CITY: CADILLAC		COUNTY: WEXFORD
CONTACT: Al Gatt , HSE Coordinator		ACTIVITY DATE: 09/07/2016
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR
SUBJECT: Site visit to introduce Gloria Torello, AQD, to permittee staff.		
RESOLVED COMPLAINTS:		

From AQD: Gloria Torello and Rob Dickman.  
From Hutchinson: Al Gatt and Tom Jackson.

Torello is now assigned to this facility. The purpose of the site visit was to introduce Gloria Torello to permittee staff.

AQD staff had to sign in by going thru the onsite training, it is an interactive electronic training in the lobby. When training is completed, the machine produces a peel and stick visitor pass complete with AQD staff's photo. The visitor's pass is worn by the visitor. When leaving, the visitor checks out at the same machine found in the lobby.

Al and Tom met AQD staff and provided a tour. Tom will send Gloria a larger scale diagram of the facility. An ROP modification will soon be finalized. When the ROP modification is final, Torello will request the permittee update their malfunction abatement plan (MAP) to identify the new ROP in the MAP.

The facility operated during the site visit. Hutchinson produces a variety of automotive parts that consist of rubber and metal components. The rubber components are manufactured on site while the metal parts are manufactured elsewhere and shipped to the facility. Various adhesives are used to bond rubber and metal together. The facility includes processes for cleaning the various metal components, molding of rubber components, and applying various adhesives to each .

Torello followed the plant thru the process flow. The emission units were observed. EUAUTODIP2's enclosure door was not shut all the way and Tom had to shut the door. Torello reminded Tom to remind his staff to make sure enclosures are kept shut. There were distinct and definite odors in the facility.

The paint booth associated with FG-RULE 287(c) is exempt under rules 287 and 287(c). Per conversation with Caryn Owens, AQD, the FG is included in the ROP because there are recordkeeping requirements in exemption 287.

On site are 70 plus rubber injection and compression presses. The ROP is written such that the presses are not emission units. There is not a presses flexible group. More presses may be installed without a permit. EUBRMOLDING sets pollutant emission limits, and limits material including, "The permittee shall not process more than 18,000,000 pounds of rubber in EURBMOLDING per year..." Rob Dickman commented the ROP was written this way because the conditions originated that way in a permit to install.

**Summary:**  
Tom will send Gloria a larger scale diagram of the facility.  
When the ROP modification is final, Torello will request the permittee update their MAP.

NAME Gloria Inello

DATE 9-21-16

SUPERVISOR 