## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Self Initiated Inspection

FACILITY: SRW, Inc Forest Home 12 Facility		SRN / ID: N7824
LOCATION: SW 1/4 NE 1/4 SEC 12 T30N R8W, BELLAIRE		DISTRICT: Gaylord
CITY: BELLAIRE		COUNTY: ANTRIM
CONTACT: JOHN STEGMAN, FIELD SUPERINTENDENT		ACTIVITY DATE: 10/25/2016
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: site visit to view stac	k after corrections to height and direction were made	
RESOLVED COMPLAINTS:		

Received an email from John Stegman on 9/28/16, indicating the CPF would begin operation on 10/3/16. SRW was issued a VN 5/31/16 for 1) stack too short; 2) stack emitting to the side instead up unobstructed upwards. In the VN response dated 6/3/16, SRW requested that the CPF not be required to fix the stack until it was going to start operating again. The above email indicated the re-start of the CPF, hence the updates to the stack.

Visited the facility on 10/25/16 with Gloria Torello of AQD. The stack height and direction had been fixed and appear in compliance of PTI 207-07.

The engine was operating. The stack has a muffler, no catalytic converter. No VE or odor from engine stack. Dehy had slight odor, no VE. The iron sponge had a door open on the unit.

Engine was operating at 900 RPM; 32 psi oil pressure.

Several contained tanks were located inside building.

NAME

DATE

SUPERVISOR