



RICK SNYDER  
GOVERNOR

STATE OF MICHIGAN  
DEPARTMENT OF ENVIRONMENTAL QUALITY  
LANSING



C. HEIDI GRETHUR  
DIRECTOR

March 27, 2018

Mr. Ray Choi  
Michigan Cleaners  
2300 West Stadium Boulevard  
Ann Arbor, Michigan 48103

Establishment Number: 8100004  
Washtenaw County

Dear Mr. Choi:

**SECOND VIOLATION NOTICE**

On February 15, 2018, the Department of Environmental Quality (DEQ), Air Quality Division (AQD), conducted an inspection of Michigan Cleaners located at 2300 West Stadium Boulevard, Ann Arbor, Michigan. The purpose of this inspection was to determine Michigan Cleaners compliance with the requirements of the federal Clean Air Act and Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451).

Specifically, this dry cleaner is subject to the federal National Perchloroethylene Air Emission Standards for Dry Cleaning Facilities, Title 40 of the Code of Federal Regulations (CFR), Part 63, Subpart M and the Public Health Code, 1978 PA 368, as amended, Dry Cleaning Establishment Rules Utilizing Class I, II, III, and IV Solvents.

On February 23, 2018, the AQD sent the company a Violation Notice citing violation discovered as a result of the inspection and requested your written response by March 16, 2018. A copy of that letter is enclosed for your reference. As of this date, we have not received your response.

Please be advised that failure to respond in written and identifying actions the company will take or has taken to resolve the cited violations may result in escalated enforcement actions by the AQD. Please provide the information requested in our February 23, 2018 letter by Tuesday, April 10, 2018, which corresponds to 14 days from the date of this letter.

Be further advised that issuance of this Violations Notice does not preclude or limit the DEQ's ability to initiate any other enforcement action under state or federal law as appropriate.

Mr. Ray Choi  
Page 2  
March 27, 2018

If you have any questions regarding the violations or the actions necessary to bring this facility into compliance, please call me at the number listed below.

Sincerely,



Jong H. Yu  
Environmental Quality Analyst  
Air Quality Division  
517-285-4201  
Fax: 517-355-3122

Enclosure

cc: Ms. Mary Ann Dolehanty, DEQ  
Mr. Chris Ethridge, DEQ  
Mr. Malcolm Mead-O'Brien, DEQ  
Ms. Karen Kajiya-Mills, DEQ



RICK SNYDER  
GOVERNOR

STATE OF MICHIGAN  
DEPARTMENT OF ENVIRONMENTAL QUALITY  
LANSING



C. HEIDI GREETHER  
DIRECTOR

February 23, 2018

COPY

Mr. Ray Choi  
Michigan Cleaners  
2300 West Stadium Boulevard  
Ann Arbor, Michigan 48103

Establishment Number: 8100004  
Washtenaw County

Dear Mr. Choi:

**VIOLATION NOTICE**

On February 15, 2018, the Department of Environmental Quality (DEQ), Air Quality Division (AQD), conducted an inspection of Michigan Cleaners located at 2300 West Stadium Boulevard, Ann Arbor, Michigan. The purpose of this inspection was to determine Michigan Cleaners compliance with the requirements of the federal Clean Air Act and Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451).

Specifically, this dry cleaner is subject to the federal National Perchloroethylene Air Emission Standards for Dry Cleaning Facilities, Title 40 of the Code of Federal Regulations (CFR), Part 63, Subpart M and the Public Health Code, 1978 PA 368, as amended, Dry Cleaning Establishment Rules Utilizing Class I, II, III, and IV Solvents.

During the inspection, staff observed the following:

Process Description	Rule/Permit Condition Violated	Comments
Commercial, Dry to Dry, Type IV Perchloroethylene dry cleaning facility	40 CFR 63.322(d)	The drying temperature was too low in drum(86°F) and finished garments were contained more than 1000ppm perc vapor.
	40 CFR 63.322(o)(1)	The monthly leak check with a halogenated hydrocarbon detector is not being performed.
	40 CFR 63.324(d)(1,2,3,4,5)	The NESHAP temperature OR pressures, leak detection, repair, and perc purchase logs are not being kept for the dry cleaning machine.
	R 325.17107(a)	The residues containing dry cleaning solvent is not being stored in a covered hazardous waste container.
	R 325.17302(2)(4)	Did not pay the 2018 dry cleaning license fee and are operating without a license.


Mr. Ray Choi  
Page 2  
February 23, 2018

Please initiate actions necessary to correct the cited violations and submit a written response to this Violation Notice by March 16, 2018, (which coincides with 21 calendar days from the date of this letter). The written response should include: the dates the violations occurred; an explanation of the causes and duration of the violations; whether the violations are ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violations, and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

If Michigan Cleaners believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violations cited above and for the cooperation that was extended to me during my inspection. If you have any questions regarding the violations or the actions necessary to bring this facility into compliance, please call me at the number listed below.

Sincerely,



Jong Yu  
Environmental Quality Analyst  
Air Quality Division/Dry Cleaning Program  
517-285-4201

cc: Ms. Lynn Fiedler, DEQ  
Mr. Christopher Ethridge, DEQ  
Mr. Thomas Hess, DEQ  
Ms. Karen Kajiya-Mills, DEQ