DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

M3333	20242	ŧ.

EACILITY: Convey Products Co	rporation d/b/a Emerald Spa Corp	SRN / ID: M3333
/		DISTRICT: Grand Rapids
LOCATION: 4150 E. Paris Ave. SE, KENTWOOD		
CITY: KENTWOOD		COUNTY: KENT
CONTACT: Paul Slagh , Genera		ACTIVITY DATE: 06/17/2015
STAFF: David Morgan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR
SUBJECT:		
RESOLVED COMPLAINTS:	***************************************	***************************************

At 10:45 A.M. on June 17, 2015, Air Quality Division staff Dave Morgan conducted an unannounced scheduled inspection of Conway Products (dba Emerald SpaCooperation) located at 4150 East Paris Avenue SE in Kentwood. The purpose of the inspection was to determine the facility's compliance with state and federal air pollution regulations as well as ROP No. MI-ROP-M3333-2011. Accompanying Air Quality staff on the inspection was Paul Slagh, General Manager.

At the beginning of the inspection Mr. Slagh indicated that manufacturing at the facility ceased on May 12, 2015. A letter was sent to the DEQ on June 15, 2015 declaring that manufacturing had ceased at the facility. AQD staff followed through with the inspection to verify the status of the equipment at the facility.

EUFABRICATION

This process consisted of a fiberglass lay-up booth, gelcoat spray booth, two resin storage tanks, pipe cementing area, foam application area, trimming/grinding booth and wood finishing area controlled by 3 baghouses. All equipment had been either removed from the facility or rendered in operable. Two of three baghouses remain, but are available for sale.

EUACRYLOBOND

This process consisted of a drying oven and two part application booth where a rigidizing material was applied to the backside of plastic spa shells. Although the booth and oven were still in place, it was clear that no production was taking place. According to Mr. Slagh, the two spray units for applying the polyurethane in the booth have been mothballed and are ready for sale.

SUMMARY

The company will need to submit an additional ROP Certification report for the first semi-annual period of 2015. The company was advised to submit a formal request to void ROP No. MI-ROP-M3333-2011.

SUPERVISOR