

November 4, 2014

Matt Deskins
Department of Environmental Quality
7953 Adobe Rd.
Kalamazoo, MI 49009

Dear Mr. Deskins:

Quali-Tone Corporation has implemented the following changes in response to the violations and conditions that occurred on September 26, 2014:

Special Condition # 3

As of now, documentation of our interlock system is and will be recorded and logged. All external and internal components will be cleaned and checked on a weekly basis including gas pressure gauges, electrodes, ignition assembly, solenoid valves, and temperature controllers to assure good operation with the afterburner and bottom burner.

Special Condition #4, #1, #3

As of now, Quali-Tone Corporation will keep a log of the burn-off temperatures including the afterburner. We are also investigating a recording device.

Special Condition #2

Thermal couples are replaced once every year to ensure correct operation. Quali-Tone Corporation's temperature controller will be calibrated once every year to maintain proper operational status.

Special Condition #4

Documentation of all repairs and or replaced parts will be logged and recorded. Furthermore, any malfunctions or troubleshooting of the burn-off will also be logged and recorded to assure proper maintenance.

If there are any questions, please contact Quali-Tone Corporation. Thank you for your time.

Sincerely,

Joseph Pitone
Quali-Tone Corporation



11-4-14 (M.A.D.)