

B1754- RVN-20170814

B1754

A Division of Ervin Industries, Inc.

915 Tabor Street
Adrian, Michigan 49221
(517) 265-6118
FAX (517) 265-5636



August 14, 2017


Mike Kovalchick
Senior Environmental Engineer
MDEQ - AQD
Jackson District Office

Mr. Kovalchick:

On 7/27/17 Ervin Amasteel Adrian received a violation notice from an inspection conducted on 7/6/17. In the notice there were three citations identified for corrective action and response.

1. EU-EAF: Baghouse-0009
 - a. Fan discharge duct leading into baghouse had a small hole that was observed to be emitting dust. The leak was immediately reported to the melting department supervisor. The melting department supervisor had already be notified of the leak that same morning, and assigned a maintenance crew to repair after shut down (11 am).
 - b. All dust boxes have had the inspection ports sealed shut until better sealing replacements can be made and installed. Additionally we're only going to install two inspection ports instead of the current five. Spilled dust on the ground was reviewed with personnel who work out at the dust collector, and is being policed.
2. FG0005: Baghouse-0005
 - a. Exhaust stack was reworked and now discharges completely vertical, and the expanded metal screen was removed by maintenance staff.

Attached you will find photographs of the corrected areas. We trust that the information presented for the cited items will address/meet the State of Michigan's expectations.

Thank you,

Richard Payne
Plant Engineer

Encl.: (6)

cc: Jim Lemon
File











