



RICK SNYDER  
GOVERNOR

STATE OF MICHIGAN  
DEPARTMENT OF ENVIRONMENTAL QUALITY  
SOUTHEAST MICHIGAN DISTRICT OFFICE



DAN WYANT  
DIRECTOR

August 6, 2015

Mr. Bryan K. Mathews, President  
H & S Propeller Shop Inc.  
8220 Old White Lake Road  
White Lake, MI 48386-1154

SRN: N6678, Macomb County

Dear Mr. Mathews:

**VIOLATION NOTICE**

On July 8, 2015, the Department of Environmental Quality (DEQ), Air Quality Division (AQD), conducted an inspection of H & S Propeller Shop Inc located at 8820 Old White Lake Road, White Lake, Michigan. The purpose of this inspection was to determine H & S Propeller Shop's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the administrative rules.

During the inspection, staff observed the following:

Process Description	Rule/Permit Condition Violated	Comments
"Model 48 BACT" Vapor Degreaser	R 336.1201	Unpermitted vapor degreaser externally vented

**- RULE 201 VIOLATION**

During this inspection, it was noted that H & S Propeller Shop Inc. had commenced operation of an unpermitted vapor degreaser at this facility. The AQD staff advised Mr. Mathews on July 14, 2015, that this is a violation of Act 451, Rule 201.

A program for compliance may include a completed PTI application for the vapor degreaser process equipment. An application form is available by request, or at the following website:

[http://www.deq.state.mi.us/aps/nsr\\_information.shtml](http://www.deq.state.mi.us/aps/nsr_information.shtml)

Be advised that Rule 201 requires that a permit be obtained prior to installation, construction, operation, reconstruction, relocation, or alteration of any process or process equipment which may be a source of an air contaminant.


**- RESPONSE/COMPLIANCE PROGRAM/CONCLUSION**

Please initiate actions necessary to correct the cited violation and submit a written response to this Violation Notice by August 27, 2015 (which coincides with 21 calendar days from the date of this letter). The written response should include: the dates the violation occurred; an explanation of the causes and duration of the violation; whether the violation is ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violation and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

If H & S Propeller Shop Inc. believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violation cited above and for the cooperation that was extended to me during my inspection of H & S Propeller Shop Inc. If you have any questions regarding the violation or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,



Kerry Kelly  
Environmental Quality Analyst  
Air Quality Division  
586-753-3746

KK/DC

cc/via e-mail: Ms. Lynn Fiedler, DEQ  
Ms. Teresa Seidel, DEQ  
Mr. Thomas Hess, DEQ  
Mr. Chris Ethridge, DEQ