

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

A398340768

FACILITY: MENOMINEE MILLWORK & LUMBER		SRN / ID: A3983
LOCATION: 901 39TH AVE, MENOMINEE		DISTRICT: Upper Peninsula
CITY: MENOMINEE		COUNTY: MENOMINEE
CONTACT:		ACTIVITY DATE: 07/19/2017
STAFF: Sydney Bruestle	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Inspection to verify compliance with State and federal air quality rules.		
RESOLVED COMPLAINTS:		

On July 19, 2017 I (Sydney Bruestle) and Joe Scanlan attempted to perform an onsite inspection of Menominee Millwork and Lumber located at 901 39th Ave. Upon arrival we were able to confirm the facility has been completely demolished. There were no remains of any buildings or equipment onsite. I will send a request to have the SRN removed from MACES.

NAME Sydney BruestleDATE 07/20/17 SUPERVISOR ELH