DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility :	Midwest Rubber Co	ompany		SRN:	A6444		
Location: 3525 RANGELINE RD P.O. Box 98						District :	Bay City
						County :	SANILAC
City: [DECKERVILLE S ta	te: MI	Zip Code :	48427	Comp Status		Non Compliance
Source Class: SM OPT OUT Staff: Adam Shaffer							
FCE Begin	Date: 3/8/2021				FCE Date	Completion ⇒ :	3/8/2022
Comments	: 2022 FCE Rep	ort					

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
03/08/2022	On-site Inspection	Non Compliance	On-site inspection.

Name: Man J. July Date: 05/23/22 Supervisor: C. Mace