DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: CLOVERLAND ELECTRIC COOPERATIVE -SRN: B6107 **DAFTER** 2535 W HIGHWAY M-28 District: Location : Marquette County: **CHIPPEWA** City: DAFTER State: MI **Zip Code**: 49724 Compliance Compliance Status: Source Class: Staff: SM OPT OUT Lauren Luce FCE Begin Date : 4/21/2022 **FCE Completion** 4/21/2023 Date: Comments: FCE complete. Facility is in compliance.

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
04/21/2023	On-site Inspection	Compliance	Targeted Inspection FY23
03/13/2023	MAERS	Compliance	SCC codes verified. MAERS and Tier 2 emission factors used. All emission units reported. Attachment provided.
08/03/2022	MACT (Part 63)	Compliance	Semiannual compliance report for MACT ZZZZ. No deviations reported. Report includes operating hours, fuel used, operational temperature averages, and operation pressure change averages for EUENGINE4.
05/19/2022	MAERS	Compliance	SCC codes verified. MAERS emission factors and limit from PTI used. Attachment provided. All emission units reported.

Name: Date: 6/1/2023 Supervisor: Midwell Waller

Page 1 of 1