## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Self Initiated Inspection** 

B/39030375			
FACILITY: ANR Pipeline - Cer	tral Charlton Compressor Station	SRN / ID: B7390	
LOCATION: 14490 Beckett Ro	ad, JOHANNESBURG	DISTRICT: Gaylord	
CITY: JOHANNESBURG		COUNTY: OTSEGO	
CONTACT:		ACTIVITY DATE: 07/15/2015	
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR	
SUBJECT: ANR multi-site visit	s to observe stacks on compressor engines		
RESOLVED COMPLAINTS:			

## On July 15, 2015 Gloria Torello of AQD visited these ANR facilities:

- B7219 South Chester,
- B7390 Central Charlton,
- B7196 Excelsior,
- B7198 Cold Springs 12 (CS12), and
- Blue Lake (BL).

Recently there were visible emissions at and over 20 percent from the CS12 Compressor Engine B. The purpose of the site visits was to observe and compare visible emissions on the compressor engine stacks at the various facilities. Torello also observed the stacks on the BL generator engines. It was a clear day with a blue sky and temps in the upper 70s lower 80s. Torello met ANR staff at the facilities and received compressor engine operating information. This is a synopsis of Torello's observations:

	B7219 South Chester	B7390 Central Charlton	B7196 Excelsior	B7198 Cold Springs 12	B7198 Blue Lake
County	Otsego	Otsego	Kalkaska	Kalkaska	Kalkaska
Contact	Charles Horrigan, Bill Klein	Jack Roggow, Bruce Bendes	Kenny Price, Mr. Gives, Duwayne Hunter	Keith Campbell	Keith Campbell
# Compressor Engines on site	2	2	2	3	3
# Compressor Engines Operating	1	1	1	1 (Unit B)	1 (Unit A)
Visible Emission %	5% or less	Less than 5%	5%	5-10%	5-10%
BL # Generator Engines on Site					3
BL # Generator Engines Operating					1 (Unit B)
Visible Emissions %					5%

Operating information will be filed with B1477.

DATE 7-28-15 SUPERVISOR