DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: Central Michigan University SRN: K2460 Location: 1720 S. East Campus Drive District: Saginaw Bay County: **ISABELLA** City: MOUNT State: MI Zip Code: 48859 Compliance Compliance Status: **PLEASANT** Source Class: **MAJOR** Staff: Benjamin Witkopp FCE Begin Date: 8/12/2018 **FCE Completion** 8/12/2019 Date: Comments: Small improvements needed in records for engine hours and use, not a VN situation.

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
08/12/2019	Scheduled Inspection	Compliance	Facility inspection
06/17/2019	MAERS	Compliance	CMU prepared the submittal and reported gasoline usage for a tank. AQD found some discrepancies in the information presented. Staff discovered it had been removed and a new aboveground tank added, The new 2 compartment tank held both gasoline and diesel. CMU then had their consultant prepare the submittal to correctly report emissions.
05/13/2019	ROP Annual Cert	Compliance	No deviations reported
05/13/2019	CAM Excursions/Exceedan ces	Compliance	None reported
05/13/2019	ROP SEMI 2 CERT	Compliance	No deviations reported

Name: 10 hate: 9-27-19 Supervisor: C. Mace