

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N020462822

FACILITY: Manthei Construction		SRN / ID: N0204
LOCATION: 1430 OLD 27 N, GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 05/09/2022
STAFF: David Bowman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled Inspection Source Compliant.		
RESOLVED COMPLAINTS:		

On 9 May 2022 I, David Bowman Inspector with EGLE AQD, conducted a scheduled onsite inspection of Bozzer Brothers, now named Manthei Construction, PTI 660-85. I met Tony - the onsite foreman. The site has been transferred to Manthei Construction and I have updated MACES to reflect the name change.

Tony told me that he had been at the site for approx. 4 years since it was acquired by Manthei Construction. He thought that they may have a copy of the PTI but was not sure. I had brought a copy of it with me for him since I was not sure that they would have gotten any copies of it from the sale.

From M32 in Gaylord travel North on Center street/Old US 27 N for approx. 3 miles. After you go through the roundabout at the high school you can see the facility on the western side of the road. They share the lot with another company and Manthei Construction is in the back building. Site was clean and organized. Parking was marked and there was no fugitive dust or odors that I could detect. The weather has been very dry for the last week and the temps today were in the high 60s and winds around 15 MPH sustained. As I watched vehicles move around there was little to no dust being kicked up into the air.

The site was in operation at the time of my inspection and actively loading a truck. There are three SC that the site is required to meet. There is no records requirements from PTI 660-85 so no records review has been completed. The site has a single silo and utilizes a bag filter system to control emissions.

SC 10 Rule 331 – the particulate emission from the silo shall not exceed 0.10 pounds per 1,000 pounds of exhaust gases, calculated on a dry gas basis

SC 11. Visible emissions from the silo shall not exceed a 6 minute average of 20% opacity, except as specified in Rule 201(1)(a).

SC 12 Applicant shall not operate the silo unless the fabric filter is installed and operating properly.

The Permit Engineer notes stated that the method

I used Method 22 and verified that no emissions from the silo or fugitive dust from the building was being emitted during the loading of the truck. I spoke with Tony and verified that the filters are being used and in place. All three conditions are being met from the PTI.

NAME _____

DATE _____

SUPERVISOR _____