DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Self Initiated Inspection

N183652534	· · · · · · · · · · · · · · · · · · ·	
FACILITY: H L BROWN OPERATING, REED CITY CPF		SRN / ID: N1836
LOCATION: SEC 29 T18N R10W, LINCOLN TWP		DISTRICT: Cadillac
CITY: LINCOLN TWP		COUNTY: OSCEOLA
CONTACT:		ACTIVITY DATE: 02/12/2020
STAFF: Rob Dickman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Inspection of this o	pt out source.	
RESOLVED COMPLAINTS:	* • • • • • • • • • • • • • • • • • • •	

Inspected this opt out source in response to a MAERS fee challenge received by the facility on 1/27/2020. The fee challenge letter indicated the facility has not been in operation and has been shut in since October of 2019. A review of the equipment on site demonstrated the following:

- One high pressure AST, ~1000 gallons
- One 200 bbl AST

The site itself was not being maintained for snow removal. It was secured and appeared to have not been visited recently. No compressor or glycol dehy was on site. The feed lines to the AST's on site were unhooked and shut in. The well feeds were also unhooked. A check with OOGM staff indicated the wells feeding the facility were plugged in 2019. It is recommended that the permit for the facility (#221-88) be voided and the facility removed from the MAERS system.

NAME Kellich

DATE 2/25/20 SUPERVISOR