

Moula

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N202026475

FACILITY: Fusion Flexo		SRN / ID: N2020
LOCATION: 156 10TH ST, PLAINWELL		DISTRICT: Kalamazoo
CITY: PLAINWELL		COUNTY: ALLEGAN
CONTACT: Brad Boyd , VP of Operations		ACTIVITY DATE: 07/30/2014
STAFF: Dale Turton	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Inspection and check on a letter requesting that we void two permits.		
RESOLVED COMPLAINTS:		

Fusion Flexo has purchased the former Hughes Integrated facility.

A letter was received requesting that permits numbered 932-89 and 933-89 be voided.

Upon investigation it was found that the etching machines permitted under 932-89 were removed from the facility. Staff has sent an e-mail to Lansing to have this permit voided.

Pn 933-89 is for two evaporators. One of them was removed several years earlier, but one still remains. At this time, this permit will not be voided.

The Photopolymer process is still in place. This is being operated under Rule 290. The records being kept by the company show that they have averaged 621 pounds of VOC per month over the last 2 years. This is less than the 1000 pounds per month allowed by Rule 290 in order to be exempt from needing a permit. "Solvit" and "Solvit component B" are the solvents used in the process for washing the photopolymer plates. There is a reclamation still that is used.

NAME Dale Turton

DATE 8/19/14

SUPERVISOR MA 8/20/2014