## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

| <u>U83150115528599</u>                   |                               | 1.1                         |
|--|-------------------------------|-----------------------------|
| FACILITY: Wexford County Road Commission |                               | SRN/ID: U831501155 / N 3937 |
| LOCATION: 85 West Highway M-115          |                               | DISTRICT: Cadillac          |
| CITY: Boon                               |                               | COUNTY: WEXFORD             |
| CONTACT:                                 |                               | ACTIVITY DATE: 02/19/2015   |
| STAFF: Kurt Childs                       | COMPLIANCE STATUS: Compliance | SOURCE CLASS:               |
| SUBJECT: Compliance inspe                | ection.                       |                             |
| RESOLVED COMPLAINTS:                     |                               |                             |

## Scheduled Inspection

## N3937 Wexford County Road Commission

PTI 627-93 Paint spray booth

## PTI 724-93 Waste oil burner

I conducted a scheduled inspection of the Wexford County Road Commission located at 85 M-115. This location is the road commission headquarters and houses the offices, maintenance, equipment storage and road salt/sand storage facilities.

I met with Mr. Donald Patnode, Assistant superintendent. We discussed the permits for the paint booth and waste oil burner. Mr. Patnode stated that neither has been in operation for many years. The paint booth area is now used for storage and the waste oil heater was removed long ago. Mr. Patnode stated that in never worked very well. As for maintenance painting of the equipment Mr. Patnode stated that truck boxes are now made of aluminum and don't require painting and other equipment is sent of site for sandblasting and painting.

The Road Commission also has an outdoor wood boiler that was previously inspected by AQD staff on 3/30/2011 and found to be in compliance with Rule 282. The wood stove was in operation at the time of the inspection and a water vapor plume was present as well as minimal opacity and mild wood smoke odors. It appeared to be operating properly.

Mr. Patnode agreed that both PTI 627-93 and 724-93 could be voided. On 2/20/2015 I requested the permits be voided.

DATE <u>2-20-</u>15 SUPERVISOR