

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N511659971

FACILITY: Cretens Brothers Waterbeds, Inc		SRN / ID: N5116
LOCATION: 5954 Perkins 305 Road, PERKINS		DISTRICT: Marquette
CITY: PERKINS		COUNTY: DELTA
CONTACT: Ben Cretens , Operations Manager		ACTIVITY DATE: 09/15/2021
STAFF: Sydney Hewson	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Onsite Inspection to verify compliance with PTI 1327-91 and all other applicable state and federal air quality regulations		
RESOLVED COMPLAINTS:		

On September 15, 2021 I (Sydney Hewson) performed an onsite inspection of Cretens Cabinets located at 5954 Perkins 30.5 Road in Perkins, MI. While onsite I met with Ben Cretens, Operations Manager at Cretens Cabinets.

Facility Description:

Cretens cabinets has been in business since the 1980's. In the past they made furniture, currently they make only kitchen cabinets for contractors and home owners. The facility manufactures around two kitchen cabinet orders per week and has 7 employees. Operations onsite include a sanding machine, CNC machine, saws, a spray booth, and a cabinet assembly area. The only unit that vents outside is the spray booth. This was installed in the 1980's and has not been modified. The booth vents out the side of the building, the facility changes the filters weekly. The only material used in the spray booth is a precatylized laquer, the facility uses around 15 gallons/week or 60 gallons/ month. This is below the permit exemption identified in rule 287(c) of 200 gallons/month.

PTI 1327-91:

This Permit to Install covers a wood chip handling machine that no longer exists. The facility is aware they can void the PTI if they choose.

Compliance Determination:

At the time of my inspection it appeared the facility was in compliance with PTI 1327-91 and all other applicable state and federal air quality regulations.



Photo Description: Spray Booth




Photo Description: Sanding Machine attached to a baghouse venting only indoors.



Photo Description: Wood finishing machine attached to a baghouse venting only indoors.




Photo Description: Vent from spray booth on the side of the facility

NAME SP #21

DATE 9/23/21

SUPERVISOR EDR