DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : N	orthern Oaks Recycling and Disposal Facil	SRN :	N6010		
Location : 513 N. County Farm Road			District :	Saginaw Bay	
			County :	CLARE	
City: HAI	RRISON State: MI Zip Code : 486	25 Comp Statu	bliance s :	Compliance	
Source Class	: MAJOR	Sta	ff: Gina l	McCann	
FCE Begin Date : 7/16/2017 FCI Date			E Completion	11/16/2017	
Comments : FCE. Non-compliance on inspection 10/19/2017. Map identifying asbestos placement was missing several loads received. Facility resolved the violation by updating their map within a day of the inspection.					

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments	
11/03/2017	Stack Test	Compliance	Test Report for Co, NOx, and VOC emissions from EUICENGINE1. Test results NOx 0.8 g/bhp-hr CO 2.20 g/bhp-hr VOC 0.1 g/bhp-hr Emissions test compliant with ROP limits and NSPS JJJJ limits. glm	
10/31/2017	ROP Other	Compliance	Tier 2 Report	
10/19/2017	Scheduled Inspection	Non Compliance	Inspection of MI-ROP-N6010- 2013 Facility was in non-compliance with NESHAP for asbestos. Map identifying placement of asbestos was missing several loads received.	
09/15/2017	ROP Semi 1 Cert	Compliance	No deviations	
09/06/2017	Stack Test Observation	Unknown	NSPS JJJJ testing	

Name: Uninh. M Date: 11/20/17 Supervisor: ______ Page 1

Hace

Page 1 of 1