DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Scheduled Inspection

N613741444

FACILITY: QUICKSILVER RESOURCES INC HAYES 29		SRN / ID: N6137
LOCATION: SW4 SW4 T29N R4W SEC 29, HAYES TWP		DISTRICT: Gaylord
CITY: HAYES TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 06/20/2017
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: scheduled inspection	n and records review	
RESOLVED COMPLAINTS:		

This report is for a FY17 minor source file inspection for N6137 Breitburn, PTI 695-96. This source is located in Section 29, T29N R4W, Otsego County.

N6137 PTI 695-96 file is marked as void however the is still on the minor source inspection list. Further review finds:

N6137 PTI 695-96 was void 6/28/05 – AQD void letter indicates that PTI 695-96, along with PTI's 4-96 and 4-96A, were all voided and all now covered by PTI 86-05 (SRN N5831).

N5831 PTI 86-05 was issued 6/28/05, then voided 3/20/06, and is now part of ROP MI-ROP-N5831-2014a, Breitburn Operating Wilderness Hayes.

N5831 was inspected on 1/6/17 and determined to be in compliance.

This equipment is now covered under a different SRN and ROP permit. Therefore, N6137 PTI 695-96 should be removed from the minor inspection list.

MACES facility information screen will be updated to reflect this information.

NAME Focky Radu OSICi

date <u>9/11/17</u>

SUPERVISOR