## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

| Facility :                          | TRENDWELL ENERGY CORP - Vienna 31 |        |    |            |                          |                     | SRN :      | N6150          |
|-------------------------------------|-----------------------------------|--------|----|------------|--------------------------|---------------------|------------|----------------|
| Location : NW NE SE T30N R1E SEC 31 |                                   |        |    |            |                          |                     | District : | Gaylord        |
|                                     |                                   |        |    |            |                          |                     | County :   | MONTMORENCY    |
| City :                              | VIENNA TWP                        | State: | MI | Zip Code : | 49756                    | Complia<br>Status : | nce        | Non Compliance |
| Source C                            | lass : SM OPT                     | OUT    | D. |            |                          | Staff :             | Gloria     | Torello        |
| FCE Begin Date : 7-14-2013          |                                   |        |    |            | FCE Completion<br>Date : |                     | 7/14/2014  |                |
| Commen                              | ts: 2014 FCE                      |        |    |            |                          |                     |            |                |

List of Partial Compliance Evaluations :

| Activity Date | Activity Type                 | Compliance Status | Comments   |
|---------------|-------------------------------|-------------------|--|
| 04/16/2014    | Malfunction<br>Abatement Plan | Compliance        | MAP  |
| 03/20/2014    | MAERS                         | Compliance        | 2013 MAERS. Did not use the control efficiencies developed thru "Emissions Check" completed by Exterran. |
| 03/11/2014    | Scheduled Inspection          | Non Compliance    | 2014 Inspection.   |

Name:

Page 1 0