

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N643139456

| | | |
|---|-------------------------------|---------------------------|
| FACILITY: Ener Vest Operating ASE 6 CPF | | SRN / ID: N6431 |
| LOCATION: T30N-R2W, Section 32, CHESTER TWP | | DISTRICT: Cadillac |
| CITY: CHESTER TWP | | COUNTY: OTSEGO |
| CONTACT: Jeff Riling , OPERATIONS MANAGER | | ACTIVITY DATE: 04/20/2017 |
| STAFF: Gloria Torello | COMPLIANCE STATUS: Compliance | SOURCE CLASS: SM OPT OUT |
| SUBJECT: Site visit to look at stack. | | |
| RESOLVED COMPLAINTS: | | |

The purpose of the site visit was to look at the stack as a follow-up to a violation notice. The VN identified the stack as being shorter than the permitted 30 feet in height. Based on a visual assessment, the stack now meets the permit requirement of a minimum of 30 feet.

MACES LOV was updated.

NAME Gloria Torello DATE 4-21-17 SUPERVISOR SN