DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: Ener Vest Operating ASE 5	SRN:	N6444		
Location: T30N-R2W, Section 35	District :	Cadillac		
	County:	OTSEGO		
	Compliance Status :	Compliance		
Source Class: SM OPT OUT	Staff: Chance	Collins		
FCE Begin Date : 12/17/2017	FCE Completion Date :	12/17/2018		
Comments: Full Compliance Evaluation Facility is in Compliance				

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
12/11/2018	Scheduled Inspection	Compliance	Scheduled Inspection for FCE
10/19/2018	Other	Compliance	Review of Records for Full Compliance Evaluation
03/05/2018	MAERS	Compliance	See MAERS for further info.

Page 1 of 1