DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

| Facility: Wolverine Power, Gaylord Generating Station | SRN: | N6833 | | |
|-------------------------------------------------------|------------------------|------------|--|--|
| Location: 2700 Millbocker Road | District : | Cadillac | | |
| | County: | OTSEGO | | |
| | Compliance Status : | Compliance | | |
| Source Class : MAJOR Staff : Caryn Owens | | | | |
| FCE Begin Date: 6/20/2022 | FCE Completion Date : | 6/20/2023 | | |
| Comments : | | | | |

List of Partial Compliance Evaluations:

| Activity Date | Activity Type | Compliance Status | Comments |
|---------------|--------------------|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 06/20/2023 | On-site Inspection | Compliance | On-Site Inspection and Records Review |
| 04/24/2023 | ROP Annual Cert | Compliance | Annual certification for MI-ROP-N6833-2021 received on time and properly certified. No deviations for the year. |
| 04/24/2023 | ROP SEMI 2 CERT | Compliance | Semi-Annual certification for MI-ROP-N6833-2021 received on time and properly certified. No deviations. |
| 04/24/2023 | ROP Semi 1 Cert | Compliance | 1st Semi-Annual certification for MI-ROP-N6833-2021 received on time and properly certified. No deviations. |
| 03/15/2023 | MAERS | Compliance | See MAERS for further info. Via paper on 3-17-23 - Checked SCC Codes, verified reported emissions were within permitted limits. Emission units matched ROP EU names. |

Name: Caupe Mens Date: 11-14-23 Supervisor: Supervisor: Dage 1 of 1