DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: RIVERSIDE - CHESTER 12 FOX CPF	SRN:	N7782
Location: NW SE NE SECTION 12 T30 R2W	District :	Gaylord
	County:	OTSEGO
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	mpliance itus :	Compliance
Source Class: SM OPT OUT	Staff: Bill Ro	gers
	CE Completion Date :	11/18/2020
Comments :	•	

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
11/18/2020	On-site Inspection	Compliance	Field inspection for FCE
11/17/2020	Other	Compliance	Record review for FCE
01/21/2020	MAERS	Compliance	2019 MAERS, Check MAERS database for any review comments

Wil	liam	J.	
Rog	gers	Jr.	

Digitally signed by: William J. Rogers Jr.
DN: CN = William J. Rogers Jr. ema*) =
rogersw@michigan.gov C = US O =
EQLE OU = Air Ovality Division
Dive: 2021.03.24 09:30*27 -04*00*

Shane Nixon Digitally signed by: Shane Nixon email = nixon oxigoned by: Shane Nixon email = nixon oxigoned call to a US o = 1/5 COL = Air Quality Division Date: 2021.03.24 09:30:48 -04'00'

Name: Date: Supervisor: