That

## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

## **FCE Summary Report**

Facility:	ALLOY RESOURCE CORPORATION					SRN:	N7888
Location :	ocation: 2281 PORT CITY BLVD					District :	Grand Rapids
	,				Ī	County:	MUSKEGON
City:	MUSKEGON	State: N	Zip Code :	49942	Compl Status		Compliance
Source Class: SM OPT OUT Staff: Eric Grinstern							rinstern
FCE Begin	Date: 1/9/2019				FCE Date	Completion :	1/9/2020
Comments	<b>.</b>						
							•

## List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
12/11/2019	Scheduled Inspection	Compliance	Unannounced inspection
08/13/2019	MACT (Part 63)	Compliance	Semiannual Compliance with Subpart RRR The facility reported two deviations - 3/14/19 - 3/15/19 - lime feed blower failure. Resulted in a maximum of 2hrs with no lime feed. Lime was manually fed through the carbon system at a rate of 40 pounds per hour while the lime system was repaired.  6/10/19 - 7/1/2019 - facility revised procedures and extra calibration to improve false alarm reports for the blds.
06/03/2019 MAERS		Compliance	Report appeared to account for all applicable emission units and emissions.

Activity Date	Activity Type	Compliance Status	Comments
03/06/2019	MACT (Part 63)	Compliance	Semiannual Compliance with Subpart RRR Facility reported no deviations, but did provide documentation of several SSM events.  A majority of the events were associated with the carbon an lime injection systems. The facility had the carbon system rebuild to address false alarms and feeder issues. On a couple of occasions the lime system had issues that resulted in manual feeding. The facility appears to have addressed the issues in accordance with the SSMP.

Date: 1/9/20 Supervisor: