

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self initiated inspection

P003649187

FACILITY: RIVERSIDE - OLD VANDY EAST CPF		SRN / ID: P0036
LOCATION: Old Vandy East CPF, VANDERBILT		DISTRICT: Gaylord
CITY: VANDERBILT		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 06/19/2019
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Inspection in response to permit void request		
RESOLVED COMPLAINTS:		

On June 19, 2019, Jodi Lindgren and I checked this facility. AQD had received a void request for the facility permit, 15-10, and I wanted to confirm the state of the equipment on site.

The compressor engine is gone. The building which had contained it is mostly demolished. Therefore the facility has ceased operation and we should void the permit.

NAME William J Rogers L. DATE 6/20/19 SUPERVISOR 