DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

P011230710

FACILITY: Speedway SuperAmerica LLC (SSA #8808)		SRN / ID: P0112
LOCATION: 2500 North Saginaw Rd, MIDLAND		DISTRICT: Saginaw Bay
CITY: MIDLAND		COUNTY: MIDLAND
CONTACT:		ACTIVITY DATE: 08/05/2015
STAFF: Sharon LeBlanc	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: confirmation of facilit	y status- alternate site to be selected	
RESOLVED COMPLAINTS:		

On August 5, 2015, AQD District Staff conducted a scheduled site inspection for remediation system at Speedway No. 8808 facility, Saginaw Road, Midland Michigan. Information provided by District RRD inspector indicated that the system had been driven into, and was not operational. Upon arrival at the site, the treatment system was not locatable. Upon return to the office District Staff confirmed with the environmental consultant for the facility that the treatment system had been removed from site for repairs. Company asked that the permit be left open until they determined whether or not future remediation would require a change in equipment or technology. sgl

HIIBRUC. 1 MAX NAME

DATE 8/201/2015 SUPERVISOR C- Have