

P1045  
MANILA

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

P104549475

FACILITY: Christman Construction, Inc.		SRN / ID: P1045
LOCATION: 11897 Belden Court, LIVONIA		DISTRICT: Detroit
CITY: LIVONIA		COUNTY: WAYNE
CONTACT: Hunter Hanson , Assistant Project Manager		ACTIVITY DATE: 07/02/2019
STAFF: Todd Zynda	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: July 2, 2019 Inspection		
RESOLVED COMPLAINTS:		

Date of Investigation: July 2, 2019  
 Date of Report: July 11, 2019  
 Source: Christman Constructors, Inc.  
 SRN: P1045  
 Address: 11897 Belden Court, Livonia, Michigan  
 Facility Staff Present: Hunter Hanson, Assistant Project Manager  
 DEQ-AQD Staff Present: Todd Zynda, Air Quality Division, Detroit District Office  
 Time of Investigation: 2:55 PM to 3:05 PM


**Summary of Facility Visit and Compliance Status:**

Christman Constructors, located at 11897 Belden Court, Livonia, Michigan, was identified as a targeted inspection for 2019 due to the close proximity to ambient air trichloroethylene (TCE) concentrations that were detected as part of the Ford Beacon Project indoor air monitoring at addresses along Belden Court. For information regarding the ambient air sampling conducted as part of the Ford Livonia Transmission Plant remedial investigation, please see SRN A8645, MACES report CA\_A864547612. There are no records of air quality permits on file for this facility.

On July 2, 2019 Mr. Todd Zynda arrived at 2:55 PM at 11897 Belden Court and was greeted by Mr. Hunter Hanson, Assistant Project Manager. According to Mr. Hanson, operations at the location are mainly office space for project management. During the inspection the office space was observed. There is a small warehouse area on the west side of the building that contained storage of construction materials and equipment (forklift, boxes, pallets etc).

According to Mr. Hanson, the facility does not operate any of the following equipment: boilers, cold cleaners, or emergency generators.

Operations at the facility do not appear to be subject to air quality rules or regulations. The source is considered to be in compliance for the reason that no air emissions activity occurs at this address.

NAME 

DATE 7/11/19

SUPERVISOR 