

# MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY

## WASTE AND HAZARDOUS MATERIALS DIVISION

### Public Record – Summary Information on Underground Storage Tanks (USTs)

#### General Information

Posted Date: December 31, 2009

Total Number of UST Facilities: 7,292  
Total Number of USTs: 19,632

#### Summary Information for On-Site Inspections

Number of UST Facilities Inspected: 2,336  
Inspection Period Dates: **2008-10-01 to: 2009-09-30**  
Percent Compliance (Combined Measure): 46%

Note: Tank, facility, and on-site inspection information is based on data as recorded in the Storage Tank Information Database (SID).

On-site inspections measure compliance based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#) .

#### Summary Information for Releases

Number of Confirmed UST Releases Reported: 183 <sup>1</sup>

Release Reporting Period Dates: **2008-10-01 To: 2009-09-30**

#### Summary Information for Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	31	18.5%					31	100%								
Piping	0															
Dispenser	0															
STP	0															
Delivery Problem	4	2.4%			2	50%	1	25%							1	25%
Other	133	79.2%					25	33.9%					93	69.9%	15	11.3%
Totals	168	100%			2	1.2%	57	33.9%					93	55.4%	16	9.5%

# =number, % = percent of total number

Note: Release, source and cause information is based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#). Source and cause data were collected using the rules for site characterization and cleanup as given in [Part 213, Leaking Underground Storage Tanks \(LUST\)](#), of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

You can obtain site-specific UST information from [Underground Storage Tank List](#).

<sup>1</sup> Number of releases reported can be greater than source totals because some reports are for releases that occurred in a previous reporting period.