

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

A138735259

FACILITY: Dayco Products, LLC		SRN / ID: A1387
LOCATION: 215 INDUSTRIAL DR, HILLSDALE		DISTRICT: Jackson
CITY: HILLSDALE		COUNTY: HILLSDALE
CONTACT:		ACTIVITY DATE: 06/29/2016
STAFF: Brian Carley	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced, Scheduled Inspection		
RESOLVED COMPLAINTS:		

Facility Contact: Dianne Horton, Site Manager  
Telephone: 517-439-0689 ext. 1704  
Email: [dianne.horton@dayco.com](mailto:dianne.horton@dayco.com)

Zack Durham and I arrived at the facility and were introduced to Ms. Dianne Horton, Site Manager for Dayco Products. After giving her the Environmental Inspection pamphlet and quickly going over it, I told her that we were there to determine the facility's compliance with Rule 290.

The company receives mats of rubber material which are loaded into the mixing mill in 100 pound batches. The mixing mill consists of two rollers that heat and press the material into a sheet that is passed over to the batching machine, where the material is allowed to cool and then cut to a rough size. The rough cut material is then transferred to the presses. There are six steam presses and two electrically heated presses. The molding presses cut the material into different sized strips to meet customer specifications.

The two paint booths the company once had have been removed and replaced with a test lab. I determined that they were in compliance and after seeing their process, I don't see a need for inspections in the future unless they get a new air permit. We thanked her for her time and left.

NAME Brian Carley DATE 6/30/16 SUPERVISOR [Signature]