

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

A304846943

FACILITY: CADILLAC PRODUCTS		SRN / ID: A3048
LOCATION: 7000 E 15 MILE RD, STERLING HTS		DISTRICT: Southeast Michigan
CITY: STERLING HTS		COUNTY: MACOMB
CONTACT: Tim Rosso , Controller/Facility Manager		ACTIVITY DATE: 11/13/2018
STAFF: Shamim Ahammod	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Conducted a scheduled inspection of Cadillac Products Inc.		
RESOLVED COMPLAINTS:		

On Tuesday, November 13, 2018, at about 11:00 AM, I, Shamim Ahammod, Michigan Department of Environmental Quality-Air Quality Division (MDEQ-AQD) staff, conducted a scheduled inspection of Cadillac Products Inc. (SRN: A3048) located at 7000 E 15 Mile Road, Sterling Heights, Michigan. The purpose of the inspection was to determine the company's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Air Pollution Control Rules; and the conditions of Permit to Install Number (PTI): 197-91 and PTI No: 797-89.

#### SOURCE DESCRIPTION:

The facility obtained two Permits from the Air Quality Division, Michigan Department of Environmental Quality. Permit to Install Number: 197-91 was issued for an adhesive spray booth and Permit to Install Number: 797-89 was issued for a flexographic printing operation of adhesive and ink onto polyethylene films.

#### INSPECTION:

At the time of inspection, I found the building main entrance door was closed. Parking lots were empty around the building. While looking through the windows, I did not find anyone inside the building. I also did not see any one outside the building. I contacted, Mr. Tim Rosso, Controller/Facility Manager, via phone. During our phone conversation, he told me that all equipment was idled by the end of 1999 and the equipment was either sold or scraped by 2008. He also stated that the building is now vacant and is listed for lease. They do not have any future plans to hold any production at the facility.

Via email, he sent me a few pictures where machinery and water tanks are used to locate. It appears to me the building is empty now and the equipment was removed from the facility. The pictures are attached to this inspection report. Mr. Tim Rosso sent an email request to Ms. Sue Thelen, of the AQD Permit Section to void the following permits

- Permit to Install Number: 197-91
- Permit to Install Number: 797-89


Based on the onsite inspection, and phone conversation with facility staff, the facility no longer operates at this location. Hence, compliance with applicable requirements was not determined.




**Image 1(Building inside1) :** Building Inside




**Image 2(Building inside) :** Building inside picture-2



**Image 3(Buidling inside)** : Building inside picture 3



**Image 4(Buidling inside)** : Building inside picture-4

NAME 

DATE 11.27.2018 SUPERVISOR BK