

DEPARTMENT OF ENVIRONMENTAL QUALITY  
 AIR QUALITY DIVISION  
 ACTIVITY REPORT: Self Initiated Inspection

B147729507

FACILITY: LAFARGE MIDWEST INC.		SRN / ID: B1477
LOCATION: 1435 Ford Ave., ALPENA		DISTRICT: Gaylord
CITY: ALPENA		COUNTY: ALPENA
CONTACT:		ACTIVITY DATE: 05/21/2015
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MAJOR
SUBJECT: View Quarry		
RESOLVED COMPLAINTS:		

While in Alpena, AQD staff viewed the Quarry at approximately 4:40 p.m. Dust was observed behind the large piece of equipment that transports material to the landfill.

NAME Gloria Torello DATE 5-26-15 SUPERVISOR 