

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

<b>Facility :</b> Morton Salt, Inc.	<b>SRN :</b> B1824
<b>Location :</b> 180 6th Street	<b>District :</b> Cadillac
	<b>County :</b> MANISTEE
<b>City :</b> MANISTEE <b>State:</b> MI <b>Zip Code :</b> 49660	<b>Compliance Status :</b> Compliance
<b>Source Class :</b> MAJOR	<b>Staff :</b> Rob Dickman
<b>FCE Begin Date :</b> 8/1/2018	<b>FCE Completion Date :</b> 8/13/2019
<b>Comments :</b>	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
08/13/2019	Scheduled Inspection ✓	Compliance	Scheduled inspection of this major source.
07/26/2019	ROP Semi 1 Cert ✓	Compliance	No deviations noted.
07/25/2019	Excess Emissions (CEM) ✓	Compliance	EU#6Boiler - Excess Emissions Reporting for second quarter of 2019, report OK, no EE's or monitoring system downtime reported.
07/25/2019	CAM Excursions/Exceedances ✓	Compliance	Excursions and system downtime contained within the same report. Zero downtime and excursions reported. Typical for this source.
07/25/2019	CAM monitor downtime ✓	Compliance	Excursions and system downtime contained within the same report. Zero downtime and excursions reported. Typical for this source.
07/25/2019	NSPS (Part 60) ✓	Compliance	EuPellet Cooling Scrubber excursions from flow and pressure drop. This reporting is required by 40 CFR 60.676(d and e). Measurements cannot exceed +/- 30% of readings determined by most recent stack testing. Report good, no excursions reported.
04/18/2019	Excess Emissions (CEM) ✓	Compliance	EU#6Boiler - Excess Emissions Reporting for first quarter of 2019, report OK, no EE's or monitoring system downtime reported.
02/14/2019	MAERS ✓	Compliance	See MAERS for Further Info.

Activity Date	Activity Type	Compliance Status	Comments
02/07/2019	Excess Emissions (CEM) ✓	Compliance	EU#6Boiler - Excess Emissions Reporting for fourth quarter of 2018, report OK, no EE's or monitoring system downtime reported.
02/07/2019	CAM Excursions/Exceedances ✓	Compliance	Excursions and system downtime contained within the same report. Zero downtime and excursions reported. Typical for this source.
02/07/2019	CAM monitor downtime ✓	Compliance	Excursions and system downtime contained within the same report. Zero downtime and excursions reported. Typical for this source.
01/29/2019	NSPS (Part 60) ✓	Compliance	EuPellet Cooling Scrubber excursions from flow and pressure drop. This reporting is required by 40 CFR 60.676(d and e). Measurements cannot exceed +/- 30% of readings determined by most recent stack testing. Report good, no excursions reported.
01/17/2019	ROP Annual Cert ✓	Compliance	Annual and Semi Annual contained within the same report. No deviations reported.
01/17/2019	ROP SEMI 2 CERT ✓	Compliance	Annual and Semi Annual contained within the same report. No deviations reported.
10/17/2018	Excess Emissions (CEM) ✓	Compliance	EU#6Boiler - Excess Emissions Reporting for third quarter of 2018, report OK, no EE's or monitoring system downtime reported.
09/21/2018	ROP Semi 1 Cert ✓	Compliance	No deviations noted.
09/21/2018	CAM monitor downtime	Compliance	EU#6 Boiler CAM excursions and monitor downtime contained within the same report. No excursions reported.
09/21/2018	CAM Excursions/Exceedances ✓	Compliance	EU#6 Boiler CAM excursions and monitor downtime contained within the same report. No excursions reported.
08/27/2018	NSPS (Part 60) ✓	Compliance	Scrubber pressure and liquid flow rate exceedance report per 40 CFR Part 60, Subpart OOO and special condition EUPELLET COOLING, VII.4, ROP MI-ROP-B1824-2015. Report OK, no exceedances reported.
08/23/2018	Stack Test	Compliance	

Name:  Date: 9/10/19 Supervisor: 