

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

B558753175

FACILITY: Lambda Energy Resources LLC - Mayfield 23		SRN / ID: B5587
LOCATION: Center Rd., KINGSLEY		DISTRICT: Cadillac
CITY: KINGSLEY		COUNTY: GRAND TRAVERSE
CONTACT:		ACTIVITY DATE: 04/01/2020
STAFF: Kurt Childs	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Compliance Check Inspection.		
RESOLVED COMPLAINTS:		

**Compliance Check Inspection
Lambda Energy Resources LLC
B5587 Mayfield 23 CPF**

This inspection was conducted to fulfill the AQD's responsibility to ensure protection of the public health under the limitations inherent during the COVID 19 disease outbreak. This inspection was observational in nature and did not involve any face to face contact with source employees.

While in the area for a scheduled inspection on April 1, 2020, I conducted a compliance check inspection of the Mayfield 23 CPF and observed the following:

PTI or ROP: PTI 193-08

Facility Operating Status: No, plant shut-in and gate locked.


Equipment Operating: None.

Any Visible Emissions?: No, no flame at flare.

Any Odors?: No.

Any Unusual Activities (new construction, new equipment, evidence of spills, etc.)?: No

Any Compliance Concerns?: No.

NAME 

DATE 4-1-20

SUPERVISOR 